Ansal Heights Sector 92 Specifications



CALL: +91-9654953152

Structure				
Earth Quake Resistant RCC Framed Structure with Brick Partition Walls				
Flooring				
Living/Dining	-	Vitrified Tiles		
Bedrooms	-	Vitrified Tiles Laminated Wooden Flooring in One Bedroom		
Toilets	-	Antiskid ceramic tiles		
Kitchen	-	Vitrified Tiles		
Verandah & Balcony	-	Antiskid ceramic tiles		
Common Staircase & Landing	-	Granite up to 1st Floor mid landing and Balance area Kota Stone till Terrace.		
Main Lift Lobby & Common Passage at every floor	-	Designed flooring in granite/ Vitrified Tile/ Designer mosaic tile.		
Toilet Dado	-	Ceramic tiles dado up to door level (7'-0")		
WC	-	EWC floor mounted off white shade with low level Cistern		
Wash Basin	-	Off white shade		
Fittings	-	CP Fittings of standard make		
Other fixtures	-	Mirror over wash basin in all toilets Towel rail/ring		
Water supply	-	Provision for Hot & Cold water supply		
Kitchen Dado Working top Sink Fittings Water supply	-	Ceramic tiles dado up to 2'-0" high above the working platform. Granite Stone Stainless steel sink with single bowl & drain board CP Fittings of standard make Provision for Hot & Cold water supply		
Joinery Door Frame Door Shutters a.) Main Door b.) Bed Room/ Kitchen/ Toilet c.) Mumty Window frame & shutter Wardrobes		Ceramic tiles dado up to 2'-0" high above the working platform. Granite Stone Stainless steel sink with single bowl & drain board CP Fittings of standard make Provision for Hot & Cold water supply Flush Door painted UPVC/Aluminium Only niches shall be provided.		

Common Staircase handrail	-	Designed handrail		
Electrical & plumbing				
Electrical work Plumbing work Lifts Genset Fire Power Back Up	-	Copper wiring in concealed PVC conduits, sufficient light and power points with designer modular switches. One telephone point in Drawing Room and each bed room. G.I., C.I/PVC SWR grade. Pipes of standard quality. Provision for geyser points in all toilets. Provision for Aqua Guard point above counter Modern elevators with genset back up and tastefully done up interior. Genset back up for essential services. Wet risers installed at every floor landing. 2 KVA – 2 BHK		
		3 KVA – 3 BHK / 4 BHK		
Internal finish				
Walls Ceiling	1 1	Oil Bound Distemper White Color Distemper P.O.P. Cornice in living and dining room.		
External finish				
Textured Paint/Weather proof paint.				